

Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Development of Slab Drain from 15th Cross to SWD Drain in Side J.P.Park in Ward No.17 in RRN Zone
2	Administration Approval & Date	AC/RRN/AS/167/12-13 Dtd 23-05-2012 by AC (RRN)
3	Technical Sanction Estimate No. & Date	EE/RRNZ/TS/81/12-13 dtd:06-06-2012 by EE (RRN)
4	Estimate Amount	Rs.19.95/- Lakhs
5	Job Code No.	017-12-000085
6	P-Code	P-2570
7	Agreement No & date	EE(P)/RRN/AG No./124/2012-13 Dtd.12-10-2012
8	Work order Number & Date	EE/Proj/RRN/W.O/124/2012-13 Dtd.12-10-2012
9	Contract Amount as per Agreement	20,84,812/-
10	Bill Amount	Rs.20,73,556/-
11	B.R. No. & Date	161/2012-13 dt.29-08-2013
12	Agency	K.Sudhakar
13	M.B. Number & Page No. of Measurement records	1389/ Pages 138815 to 138823
14	Date of Inspection	6/7/2015
15	Enclasures	1) Extract of MB No.1389 Page No.138822/2 2) 4 Number of photos taken during inspection
16	Inspection Report	I have inspected the abm site, along with the concerned officials. The measurements were checked by me and it is found to be Satisfactory

EE (P) RR Nagara

Executive Engineer (Project)

Rajarajeshwari Nagar Zone

Bruhat Bengaluru Mahanagara Palike

(R.Sathyanarayana)

Inspection Report officer,

6/7/2015

Geodhu Skol MEASUREMENT BOOK

Date	Full description, etc., of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8

29/8/13

29/8/13

29/8/13

6/7/2015
R. S. Thyagaraj
Inspection Officer